

BID TAB FOR: Landmark Building Roof Replacement - Rebid FILE NO. 2009-032-01

BID DATE: September 6, 2011

CODE: 42272.P10014

REF. NO.	ITEM NO.	DESCRIPTION	QTY.	UNIT	ENGINEER'S ESTIMATE PRICE	ENGINEER'S ESTIMATE AMOUNT	*1. Cardinal Maintenance AMOUNT	2. Carmen Construction AMOUNT	AMOUNT	
1	103.05	CONTRACT PERFORMANCE BOND	1	L.S.	\$11,000.00	\$11,000.00	\$10,500.00	\$10,500.00	\$8,000.00	\$8,000.00
2	624	MOBILIZATION	1	L.S.	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00
3	SPEC	ALL TUCKPOINTING	76	SF	\$10.00	\$760.00	\$24.00	\$1,824.00	\$24.00	\$1,824.00
4	SPEC	REMOVE ALL ASBESTOS CONTAMINATED MATERIAL AND ASSOCIATED DEMOLITION ALL WORK NOT INCLUDED IN REF. NOS.	1	L.S.	\$90,000.00	\$90,000.00	\$151,200.00	\$151,200.00	\$60,000.00	\$60,000.00
5	SPEC	1,2,3,4 & 6 ALL MASONRY DEMO AND RESTORATION (INCLUDING CHIMNEY DEMOLITION) NOT INCLUDING REF. NO. 3 TUCKPOINTING	1	L.S.	\$103,240.00	\$103,240.00	\$82,354.00	\$82,354.00	\$179,000.00	\$179,000.00
	SPEC	INCLUDING REF. NO. 3 TUCKPOINTING	1	L.S.	\$58,000.00	\$58,000.00	\$83,910.00	\$83,910.00	\$96,000.00	\$96,000.00
TOTAL CONSTRUCTION COSTS						\$278,000.00		\$344,788.00		\$359,824.00
+/- ENGINEER'S ESTIMATE								+24.0%		+29.4%

* Ref. #3 - Unit price not supplied in bid book