

III. Summary Data

This section provides information on the as-built condition, photos and materials that were a result of the project. Representative photos were taken at approximately 200 ft intervals. The project stationing began at 1+00 with the actual start of construction and/or blending to existing stream at approximately station 2+00. Attachment A provides as-built cross sections and longitudinal profile. Attachment B (Maps 1-6) provides a site overview and location of pertinent features and photo locations.



Figure 1. ST 2+50 looking downstream



Figure 2. ST 4+00 looking downstream



Figure 3. ST 6+00 looking downstream



Figure 4. ST 8+00 looking upstream



Figure 5. ST 10+00 looking downstream



Figure 6. ST 12+00 looking ups from Seiberling St bridge



Figure 7. ST 14+00 looking downstream



Figure 8. ST 16+00 looking downstream



Figure 9. ST 18+00 looking downstream



Figure 10. ST 20+00 looking downstream



Figure 11. ST 22+00 looking upstream



Figure 12. ST 24+00 looking downstream